Version 19
Software Update Details

## Problem Fixes in Version 19.0.1 (03-Aug-2015)

Component Editing
o    When editing a component, the drop-down list of library names on the Packages tab was empty.

Gerber Output
o    The default setting for "X2 in G04 comments" should be "True" so that all Gerber data being generated can contain X2 commands. Placing X2 in comment fields allows compatible readers to detect the X2 commands without causing issues in non-compliant readers.

Import CSV
o    Importing component placement CSV files was not using component positions as being relative to the design coordinate origin.

Pour Copper
o    Several design files were failing to pour due to the same internal issue with the internal geometry package.

Tool Bar
o    Two incorrect icons were being displayed on the standard Edit toolbar.