

Version 14.0.1
Software Update Details
Release Date 29-Jul-2010

Problem Fixes in Version 14.0.1 : 29-Jul-2010

Cut to Block

- Some connections were not being 'cut' in the correct place, leading to the wrong number of block ports being created.

Databook

- The Library Databook did not 'track' the current selected library so it proved difficult to make it display information about libraries from another folder. It should now track the currently selected Component library when the Databook is opened or refreshed.

Design Rule Check

- Progress bar not being updated when running 'Copper Verification' check.

Display

- The display dialog in a Schematic design still included the 'old' colour settings for Screen Grid.

Excellon (N.C.Drill) Output

- Most drill files were being generated with no drill data in them.

Forward Design Changes

- When a component in PCB was being updated due to a change in Package, the component name was sometimes being shifted a long way from the original component position.

Grids

- If all grids were marked as 'draw first', then display of grids could not be switched off.
- Ruler Stops were always being drawn first (behind design items).
- Changing grid while moving an item was not snapping the item onto the new grid.

Plotting & Printing

- The settings for plated/unplated round/slot holes were not being saved to Plot Job files for Drill Ident plots.
- The checkboxes for selecting inclusion of plated/unplated board outlines on normal plots were no longer visible.

Pro-Router

- The Pro-Router was not displaying it's Report on the screen at the end of the routing process.

Save To Library

- If a new library was created from the Save Items To Library dialog, this new library did not appear in the list of available libraries unless the folder containing that library was disabled and re-enabled, or the application restarted.

Setup

- Installing V14 over an existing previous version was not putting the new Report Templates into the template folder used by the existing application. As a result those new reports were not appearing in the list on the Reports dialog.